٥

Work Order ID 75579 October-25-11 3:12:23 PM		*75579*						, QT*C		Page 1	
Revision ID:	D3325-041			Accept	*N900	040	100)* s	etup Star	1 71	S1*
		Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item 1 Customer:	D:				' ^N	S2*
Approvals:	Process Plan QC:	: MILI	Date: 11 10	2≤Tooling: SPC (Y/N):		ate:	- 	F	tun Star Stoj	"1/	R1* R2*
Sequence ID/ Work Center II) 1	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revis	ion Nbr									
D3325	Rev B	1									* *
1 AA Large Fab Large Fab	ļ	QtyPart Nu 2D3325-1E 3D3325-3Ii 2D3325-5F	as per Dwg D3325 mber Description indTube 4/09/ interior Tube 4/109/ ull Lengh Tube 44/109/ ts appropriately	ンタ	PC 11.	// · Ø	3				
	•	3-Drill and	all markings from materia Weld as per Dwg D3325 eel Rod 118875	& OSI 004							/ ₈ .

400 man . 168

W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
'									
 									
									<u>'</u>
Part No		PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	<u>.</u>
	R	esolution:	Dispositio	n:	QA: N/C C	losed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NCI	7)			
DATE	STEP	Description of NC	8		ction B		cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	otion Sign & Date		ion C	Chief Eng	QC Inspector
	1				l			}	

Work Orde		579		*755	579*							Page 2	
Revision ID:	D3325-041 Basket Lid Ass	comply		Accept	*N900	040	100)*	Setup	Start Stop	1.71	S1*	
	25/10/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item II Customer:	D:				·	"N	S2*	
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop	"I V	R1* R2*	
Sequence ID/ Work Center II 110 *110* QC Quality Control	D	Operation Description QC9- Inspect visual per Memo	QSI004- Fusion Welds	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Qt	y	Reject Number	Insp. Stamp	
120 *120* QC Quality Control		QC5- Inspect part comp Memo	leteness to step on W/O	0.00				W)	· (\	<u>-</u> _03((
121 *171* HandFinish		Pressure Wash per QSIO	05 4.3	0.00			\nearrow		M	1-h	/ ///	u/o3	

Hand Finishing

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
													
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date:					
		esolution:	Disposition	n;	QA: N/C C	losed:		Date: _					
NCR:		V	VORK ORDI	R NON-CONFORM	IANCE (NC	R)			**************************************				
DATE	STEP	Description of NC			ction B	Approval	Approval						
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		on C	Chief Eng	QC Inspector				
			·										
									:				
		,											
				. , , , , , , ,									
					i	1		i					

Work Order ID 75579 October-25-11 3:12:23 PM			*75579*								Page 3		
Item ID: Revision ID:	D3325-041	Accept		Accept	*N900)* 5	Setup St		*NS1*		=		
Item Name:	Basket Lid As	ssembly							S	top	*N:	S2*	
Start Date: Required Date Reference:	25/10/2011 e: 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	ID:							
Approvals:		an:	Date:	0 _		ate:		1		tart top	_	R1* R2*	
Sequence ID/ Work Center 130 *120* Powdercoat Powder Coating	(N	FINISH TIN **** 2ND COAT START TIN OVEN TEM	AE:	cessary*********	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty		eject umber	Insp. Stamp	
140 *140*		QC3- Inspect Part Finish	1	0.00				/ 8	SK 1	l- 11 -	A.		

0.00

Memo

Quality Control

W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
				(8.54)									
Part No	•	PAR #:	Fault Cate	jory:	NCR: Yes I	No DQA:	Date:						
		esolution:											
NCR:		·	WORK ORDE	R NON-CONFORM	ANCE (NCR								
DATE	STEP	Description of NC	ļ	1.77	ction B	Verification	Approval	Approval					
	J.C.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector					
				A									
•													
								-					

Work Order ID 75579 October-25-11 3:12:23 PM			*75579*								Page 4
Revision ID:	D3325-041			Accept	*N900040	1100)* s	_	tart top	*N.	S1*
	Basket Lid As: 25/10/2011 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:			3	top	*N:	ドク*
Approvals:		n:	Date:	Tooling: _	Date:		R		tart top	*NI *NI	R1*
Sequence ID/ Work Center II 150 *150* Packaging Packaging		Operation Description Identify as per dwg & Stoc Memo 755	wo	Set Up/ Run Hours 0.00	Tool ID Tool #	Plan Code	Accept Qty	Reject Qty		eject lumber	Insp. Stamp
*160 *160* QC Quality Control		QC21- Final Inspection - V	vork Order Release	0.00			4		l_	1/11 /	14)

VII-11-01

	•								
W/O:			WO	RK ORDER CHANGE	ES	· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						•			
	·								
	·								
									:
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	_ Date: _	
	Re	esolution:	Disposition	ı:	_ QA: N/C C	losed:		Date:	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
								·	
							•		
				- N - O - N - N - N - N - N - N - N - N					
								į	
		·		-					

Picklist Print

October-25-11 3:12:27 PM

Work Order ID: 75579

75579

D3325-041 Parent Item:

D3325-041

Parent Item Name: Basket Lid Assembly

Start Date: 25/10/2011

Required Date: 08/11/2011

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A05.02.09New issueKJ/JLM

IPP Rev:B 08-12-16 attach DEO DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3328-1 *D3328-1* Basket Hinge	•	Manufactured	No			100	Each	23,0000	**		11/10	0/26	
				Location WA005	33871	Loc	Oty 23 23	Loc Code	C	<u>a</u>	-		
D3349-1 *D3349-1* Spacer Bushing	:	Manufactured	No			100	Each	28.0000	**	\int_{-2}^{2}	y 111	10/2	6
- 4 -				Location	<u>1</u>	Loc		Loc Code					
,	in the second se			WA005	44401		28 28		7		<u>-</u>		
D3352-1 *D3352-1* Label Plate	:	Manufactured	No			100	Each	14.0000	1 **		1 11/	10/2	6
				Location WA005	1	Loc	<u>Oty</u> 14	Loc Code					
				WAOOJ	41925		14		7	1x)	_		
D3367-1 *D3367-1* Mounting Bracket	•	Manufactured	No			100	Each	20.0000	2 **	$\frac{1}{2}$	/ 11,	/10/	26
				Location	<u>1</u>	Loc		Loc Code					
				WA005	43228		20 20		_	$\widehat{(2)}$	-		

Dart Aerospace Ltd	D	art	Aer	osp	pace	Ltd
--------------------	---	-----	-----	-----	------	-----

	•								
W/O:			WO	RK ORDER CHANG	GES	****			
DATE	STEP	PRO	OCEDURE CHAN	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							ļ		
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _	
		solution:							
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
		Description of NC			tion B	Verific		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
								`,	-
		A STATE OF THE STA							
	1	· ·	1		1	ı		I	1

Picklist Print

October-25-11 3:12:28 PM

Page 2

Work Order ID: " 75579

75579

Parent Item:

D3325-041

D3325-041

Parent Item Name: Basket Lid Assembly

Start Date: 25/10/2011

Required Date: 08/11/2011

Start Qty: 1.00

Required Qty: 1.00

M4130NTS0.500W.035

Purchased

No

100

270.9988

20.5416

**

21.62274

M4130NTS0 500W 035

4130 Square tube .500 x .500 x .035w

Location Loc Qty MAT034 270.9988 109127 216 109385 15.75 112786 39.2488

Loc Code

1,


October-25-11 3:12:28 PM

Shop Packet Print

Page 2

W/O:			W	ORK ORDER CHANGES	3				*
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				, :					
							<u> </u>		
Part No: PAR #: _		PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date: _	
Resolution:			Disposition	on:	QA: N/C Cid	osed:		Date: _	
NCR:		V	VORK ORE	ER NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC			Section B Verifica			Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	ion C	Chief Eng	QC Inspector
	, ,	<u> </u>		·					

			~*						
					**		•		




11/10/25

Dart Aeı	rospace	Ltd							• •
W/O:		A CONTRACTOR OF THE CONTRACTOR	WO	RK ORDER CHANGE	E \$				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	\:	Date: _	
٠			Disposition:						
NCR:		•	WORK ORDE	R NON-CONFORMA	NCE (NCR)			
		Description of NC		Corrective Action Section	n B		ation	Ammuoval	Ammayal
DATE	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Approval Chief Eng	Approval QC Inspector


		`									
		Description of NC		Corrective Action Section B	· · · · · · · · · · · · · · · · · · ·	Verification	Approval	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng				
				•							
				·							



DESIGN AH	DRAWN BY	DART AEROSPA HAWKESBURY, ONTARIO,	
CHECKED,	APPROVED	DRAWING NO.	REV. B
do	# H	D3325	SHEET 2 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



VIEW A-A




DEO ATTACHED



		— - - -							
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								•	
Part No: PAR #:		Fault Categ	ory:	NCR: Yes No DQA:					
Resolution:		Disposition	:	_ QA: N/C	Closed:		Date: _		
NCR:		,	WORK ORDE	R NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC			ion B Verific			Approval	Approval
 		Section A	Chief Eng	Action Description Chief Eng	Dat		on C	Chief Eng	QC Inspector
		- A.							
		·							



DESIGN PH	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
CHECKED	APPROVED	DRAWING NO.	REV. B
1 ett	─ ₩→	D3325	SHEET 3 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



(SCALE 1:2)

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	•								
W/O:			WO	RK ORDER CHANGES	3		· -		
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _	
Resolution:			Disposition	:	QA: N/C CI	osed:	-	Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC	Corrective Action Section B			Verificati			Approval
DAIL	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector

75579

DRAWING	NO.	TITLE		REV. B	DART AEF	ROSPACE L	TD	D.E.O. NO.		SHEET NO.	SCALE
D3325		BASKET LI	D ASSEMBL	Υ,	ENGINEE	RING ORDI	ER	D3325-B-1	ļ	SHEET 1 OF 1	NTS
DRAWN	AJS		CHECKED	A	MFG. APPR.	<i>P</i>	AF	PROVED	160	DE APPR.	
DATE	08.11	.28	DATE	08.11.28	DATE	08.12.01	DA	ATE	08.12.01	DATE 08.12.01	

1) SHEET 1 MODIFY PARTS LIST AS SHOWN:

PART LIST FOR D3325-041 BASKET LID ASSEMBLY

Part No.	Quantity	Description
	1	

IS:

	1	
	V	
MS20600AD4W5	32	RIVET
	1	

WAS:

	 1	T
MS20600AD4W3	32	RIVET
	1/	

2) UPDATE SHEET 3 DETAIL B ACCORDINGLY.

COPYRIGHT © 2008 BY DART AEROSPACE LTD

THIS DOGMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dail Ac	iospace L	.tu						
W/O:			W'O	RK ORDER CHANGES	3			
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approva QC Inspector
			,					
		,						
*.								
Part No	Part No: PAR #:		Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
	Res	solution:	Disposition	n:	QA: N/C Cld	sed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)		
DATE	CTED	Description of NC	Corrective Action		···		n Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC inspecto
			· ·					
	r l		1 1		I	1	1	1